

Corner originally set as a post in 1820 by John Hendricks with the following witnesses: 12" beech bearing south 67 degrees, thence east 34 links; and a 6" ironwood bearing north 3 degrees, thence west 27 links. (M. C. Atlas p. 9) A survey by H.B. Fatout on 4/4/1877 indicates a stone. (Perry Legal Book p. 32) Corner referenced by Cathcart on 3/15/54 and called a r. r. spike. Corner referenced by Wilcoxen on 8/29/75 and called a stone 15" down. Corner referenced by Wilcoxen on 9/20/79 and called a stone 15" down. Corner excavated in 1985 by Wilcoxen and a #205 cast iron Harrison Monument was set in position as the corner. Corner referenced by Gries on 9/22/87 and called a Harrison Monument. Corner referenced by Kiste on 12/20/94 and called a Harrison Monument. Corner referenced by Wilcoxen on 4/24/2000 and called a Harrison Monument. Corner excavated by Wilcoxen on 10/6/04 and a 1" riser was put on an existing Harrison Monument per paving contractor.

REF.	DISTANCE	DESCRIPTION
1.	86.31	PK nail F PwP#214-788 A. 6"up
2.	61.54	NW corner of State Farm Insurance Bldg.
3.	70.01	SW corner "
4.	119.47	Due S to NF corner of 24-14-3 : Harrison
5.	72.07	Cut 'x' in SF bolt of light pole base
6.	85.89'	PK nail F PwP#491-787 4"up